

New working group takes pole position

Powercor were happy for us to observe one of their contractor teams. Below are a few photos from the inspection site visit and some de-commissioned poles at their storage yard:



Although the issues are widespread, in some cases wood poles can last a long time. As an example, below is an identification disc from a 1934 SECV White Mahogany pole – still standing near Emerald.

